

From: [Moore, Gary](#)
To: ["Gavlas, Sean"; Lindsey, Austin](#)
Cc: [Brescia, Nicolas](#); [Criner, Jeffrey J.](#); t.a.walzer@westonsolutions.com
Subject: RE: FJ Doyle - Confirmation Summary Table (Collected 20190205)
Date: Thursday, February 7, 2019 5:36:24 PM

All:

I am not concerned about the manganese hit at this location as we will not be able to dig any deeper due to the waterlines in place. I would make sure that we confirm the depth with a measuring tape because I believe that others are much deeper than 18 inches. Also, we should put a liner on DRA08S since that is our protocol.

Thanks

Gary Moore

From: Gavlas, Sean <Sean.Gavlas@WestonSolutions.com>

Sent: Thursday, February 07, 2019 4:48 PM

To: Lindsey, Austin <Austin.Lindsey@WestonSolutions.com>

Cc: Brescia, Nicolas <brescia.nicolas@epa.gov>; Moore, Gary <Moore.Gary@epa.gov>; Criner, Jeffrey J. <Jeff.Criner@WestonSolutions.com>; t.a.walzer@westonsolutions.com

Subject: FJ Doyle - Confirmation Summary Table (Collected 20190205)

Austin,

Attached is the confirmation summary table (PDF) for DRA08S, DRA08S duplicate, and FJD04-04 confirmation samples. DRA08S failed for manganese at 18" bgs. FJD04-04 passed for all analytes. Let me know if you have any questions.

Thanks,

Sean Gavlas

Weston Solutions, Inc.

Region 6 Superfund Technical Assessment and Response Team (START)

2600 Dallas Parkway, Suite 280

Frisco, TX 75034

Cell: 609-433-8434

Office: 469-666-5560

sean.gavlas@westonsolutions.com

CONFIDENTIALITY: This email and attachments may contain information which is confidential and proprietary. Disclosure or use of any such confidential or proprietary information without the written permission of Weston Solutions, Inc. is strictly prohibited. If you received this email in error, please notify the sender by return e-mail and delete this email from your system. Thank you.